

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Heritage Environmental Venice Staging Area	Facility Location ID:	VenW01
Assessment Date :	7/21/2010	Incident Name :	BP Spill
Physical Location :	308 Halliburton Road		
City, State :	Venice, LA	County :	Plaquemines

ASSESSMENT INFORMATION

General Site Information and Observations			
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
5. How many samples were collected?			
Additional Comments : Secondary containment was being used to store containers and misc. equipment and hoses. corrective action was taken by Heritage Environmental immediately, resolution to the problem re-occurring is in progress.			